

Digital torque driver DID-4 Various functions Display section one apparatus

Yes-no decision conditions etc. can save five channels.

.. A channel is only changed even if bolting conditions change.

It is not necessary to reset up a maximum value and a minimum value one by one like former.



- The torque screwdriver is Ergonomic and light weight, yet ruggedly constructed
- Peak, Real Time and Peak Down measuring mode (selectable)
- 800 data memory
- Programmable High and Low set points with both audible beep and Green/Red LED indicator for uniform torque tightening or GO/NO GO testing
- Programmable screw tightening counter
- Programmable Auto Zero function resets unit to zero for easy operation
- Both CW and CCW operation
- ASCII format output (USB)
- Runs on internal NiMH batteries (for 12 hours) Auto shut-off after 10 min. of non-use



Specification

descent from a rise.	Specification		
Accuracy Lip.596 (499 or less digital display of LCD	Model Formula		DID-4
Accuracy Lip.596 (499 or less digital display of LCD			0.020~4 N·m 0.20~40 kgf·cm 0.20~35 lbf·in
The 4 figures digital display of LCD	<u> </u>		±0.5% (499 or less digit±3digit)
The measurement direction PP peak to peak The highest value of load is hold-displayed. TR track A display also changes with load change. PD peak-down Load catches and displays the moment included in descent from a rise. C Real-time Output Load torque value is outputted every about1/160 second. A success or failure judging function The Maximum, minimum, and the average value Data memory counts Bot odata ASCII format (baud rate 19200) If the set-up time comes, measurement value will be automatically cleared in 0.0-3.0 seconds (0.5s interval). Setup of count Power supply Charge time / use time After the neglect during 10 minutes Bit / Socket part HEX 6.35 Weight Outside-dimension CW-CCW (right and left) peak to peak The highest value of load is hold-displayed. Track A display also changes with load change. Pp peak to peak The highest value of load is hold-displayed. Real-time Output Load torque value is outputted every about1/160 second. High and low value are measurement within the limits, and can be set up. Five-set preservation is possible. The data number, the maximum, the minimum value, and the average value of memory data are displayed. 800 data ASCII format (baud rate 19200) If the set-up time comes, measurement value will be automatically cleared in 0.0-3.0 seconds (0.5s interval). Setup of count 1 to 99 count (count in a clockwise direction) Ni-MH chargeable battery 1.2Vx4cells 800mAh Charge about 3 hour /, continuation about 12-hour use After the neglect during 10 minutes Bit #1+ #2+ Bit holder One way bit holder Exclusive charger Result of calibration document / Traceability system figure Outside-dimension Outside-dimension			
PP	The measurement		
Track			neak to neak The highest value of load is hold-displayed
PD peak-down Load catches and displays the moment included in descent from a rise. Real-time Output Load torque value is outputted every about 160 second.			
Real-time Output Load torque value is outputted every about 1/ 160 second. A success or failure judging function The Maximum, minimum, and the average value Data memory counts Bot odata Ascill format (baud rate 19200) If the set-up time comes, measurement value will be automatically cleared in 0.0~3.0 seconds (0.5s interval). Setup of count Power supply Ni-MH chargeable battery 1.2Vx4cells 800mAh Charge time / Use time Auto-power-off Bit / Socket part Weight Accessories (one piece each) Outside-dimension Real-time Output Load torque value is outputted every about 1/ 160 second. Right and low value are measurement within the limits, and can be set up. Five-set preservation is possible. The data number, the maximum, the minimum value, and the average value of memory data are displayed. 800 data ASCII format (baud rate 19200) If the set-up time comes, measurement value will be automatically cleared in 0.0~3.0 seconds (0.5s interval). Setup of count 1 to 99 count (count in a clockwise direction) Ni-MH chargeable battery 1.2Vx4cells 800mAh Charge about 3 hour /, continuation about 12-hour use Auto-power-off After the neglect during 10 minutes Bit / Socket part Weight 400g Bit #1+, #2+ Bit holder One way bit holder Exclusive charger Result of calibration document Certification on calibration document / Traceability system figure Option Outside-dimension		PD	peak-down Load catches and displays the moment included in
A success or failure judging function The Maximum, minimum, and the average value Data memory counts Data output ASCII format (baud rate 19200) If the set-up time comes, measurement value will be automatically cleared in 0.0~3.0 seconds (0.5s interval). Setup of count Power supply Charge time / use time Charge about 3 hour /, continuation about 12-hour use Auto-power-off Bit / Socket part HEX 6.35 Weight Accessories (one piece each) Outside-dimension High and low value are measurement within the limits, and can be set up. Five-set preservation is possible. The data number, the maximum, the minimum value, and the average value of memory data are displayed. Bit data number, the maximum, the minimum value, and the average value of memory data are displayed. 800 data ASCII format (baud rate 19200) If the set-up time comes, measurement value will be automatically cleared in 0.0~3.0 seconds (0.5s interval). Setup of count 1 to 99 count (count in a clockwise direction) Ni-MH chargeable battery 1.2Vx4cells 800mAh Charge about 3 hour /, continuation about 12-hour use Atter the neglect during 10 minutes High and low value are measurement within the limits, and can be set up. Five-set preservation is possible. The data number, the maximum, the minimum value, and the average value of memory data are displayed. 800 data ASCII format (baud rate 19200) If the set-up time comes, measurement value will be automatically cleared in 0.0~3.0 seconds (0.5s interval).		С	Real-time Output Load torque value is outputted every about 1/ 160
Five-set preservation is possible. The Maximum, minimum, and the average value of memory data are displayed. Data memory counts Boo data ASCII format (baud rate 19200) If the set-up time comes, measurement value will be automatically cleared in 0.0-3.0 seconds (0.5s interval). Setup of count Power supply Ni-MH chargeable battery 1.2V×4cells 800mAh Charge time / use time Atter the neglect during 10 minutes Bit / Socket part HEX 6.35 Weight Accessories (one piece each) Outside-dimension Five-set preservation is possible. The data number, the maximum, the minimum value, and the average value of memory data are displayed. The data number, the maximum, the minimum value, and the average value of memory data number, the maximum, the minimum value, and the average value of memory data number, the maximum, the minimum value, and the average value of memory data number, the maximum, the minimum value, and the average value of memory data number, the maximum, the minimum value, and the average value of memory data number, the maximum, the minimum value, and the average value of memory data number, the maximum, the minimum value, and the average value of memory data are displayed. South as the set-up time comes, measurement value will be automatically cleared in 0.0-3.0 seconds (0.5s interval). Setup of count (count in a clockwise direction) Ni-MH chargeable battery 1.2V×4cells 800mAh Charge about 3 hour /, continuation about 12-hour use After the neglect during 10 minutes Bit / Socket part HEX 6.35 Weight Accessories (count in a clockwise direction) Power supply Accessories (count in a clockwise direction) After the neglect during 10 minutes Bit / Socket part HEX 6.35 Weight Accessories (count in a clockwise direction) After the neglect during 10 minutes Bit / Socket part HEX 6.35 Weight Accessories (count in a clockwise direction) Bit / Socket p	A quadada ar failura		
The Maximum, minimum, and the average value Data memory counts Bota output auto clear time Setup of count Power supply Charge time / use time Accessories (one piece each) Outside-dimension The data number, the maximum, the minimum value, and the average value of memory data are displayed. 800 data ASCII format (baud rate 19200) If the set-up time comes, measurement value will be automatically cleared in 0.0~3.0 seconds (0.5s interval). Setup of count Power supply Ni-MH chargeable battery 1.2V×4cells 800mAh Charge about 3 hour /, continuation about 12-hour use After the neglect during 10 minutes Bit / Socket part HEX 6.35 Weight Accessories (one piece each) When outputting data, the cable (USB miniB) is needed. Outside-dimension Outside-dimension			
and the average value Data memory counts 800 data Data output ASCII format (baud rate 19200) If the set-up time comes, measurement value will be automatically cleared in 0.0~3.0 seconds (0.5s interval). Setup of count 1 to 99 count (count in a clockwise direction) Power supply Ni-MH chargeable battery 1.2V×4cells 800mAh Charge time / use time Auto-power-off After the neglect during 10 minutes Bit / Socket part HEX 6.35 Weight 400g Bit #1+, #2+ Bit holder One way bit holder Exclusive charger Result of calibration document / Traceability system figure Option Outside-dimension Outside-dimension			
ASCII format (baud rate 19200) auto clear time If the set-up time comes, measurement value will be automatically cleared in 0.0-3.0 seconds (0.5s interval). Setup of count 1 to 99 count (count in a clockwise direction) Power supply Ni-MH chargeable battery 1.2V×4cells 800mAh Charge time / use time Auto-power-off Bit / Socket part HEX 6.35 Weight 400g Bit #1+, #2+ Bit holder One way bit holder Exclusive charger Result of calibration document Certification on calibration document / Traceability system figure Option Outside-dimension Outside-dimension			
auto clear time If the set-up time comes, measurement value will be automatically cleared in 0.0~3.0 seconds (0.5s interval). Setup of count 1 to 99 count (count in a clockwise direction) Power supply Ni-MH chargeable battery 1.2V×4cells 800mAh Charge about 3 hour /, continuation about 12-hour use Auto-power-off Bit / Socket part HEX 6.35 Weight 400g Bit #1+, #2+ Bit holder One way bit holder Exclusive charger Result of calibration document / Traceability system figure Option Outside-dimension Outside-dimension	-		800 data
Setup of count Power supply Ni-MH chargeable battery 1.2V×4cells 800mAh Charge time / use time Auto-power-off Bit / Socket part Weight Accessories (one piece each) Outside-dimension Outside-dimension 1 to 99 count (count in a clockwise direction) Ni-MH chargeable battery 1.2V×4cells 800mAh Charge time / use time Charge about 3 hour /, continuation about 12-hour use After the neglect during 10 minutes Bit / Socket part HEX 6.35 Bit #1+, #2+ Bit holder One way bit holder Exclusive charger Result of calibration document Certification on calibration document / Traceability system figure Outside-dimension Outside-dimension	Data output		ASCII format (baud rate 19200)
Power supply Ni-MH chargeable battery 1.2Vx4cells 800mAh Charge time / use time Auto-power-off Bit / Socket part Weight Accessories (one piece each) Outside-dimension Ni-MH chargeable battery 1.2Vx4cells 800mAh Charge about 3 hour /, continuation about 12-hour use After the neglect during 10 minutes HEX 6.35 Weight 400g Bit #1+, #2+ Bit holder One way bit holder Exclusive charger Result of calibration document Certification on calibration document / Traceability system figure When outputting data, the cable (USB miniB) is needed.	auto clear time		
Charge time / use time Auto-power-off After the neglect during 10 minutes Bit / Socket part HEX 6.35 Weight Accessories (one piece each) Bit #1+, #2+ Bit holder One way bit holder Exclusive charger Result of calibration document Certification on calibration document / Traceability system figure Option Outside-dimension Charge about 3 hour /, continuation about 12-hour use After the neglect during 10 minutes HEX 6.35 HEX 6.35 Bit #1+, #2+ Bit holder One way bit holder Exclusive charger Result of calibration document Certification on calibration document / Traceability system figure When outputting data, the cable (USB miniB) is needed.	Setup of count		1 to 99 count (count in a clockwise direction)
Charge time / use time Auto-power-off After the neglect during 10 minutes Bit / Socket part HEX 6.35 Weight Accessories (one piece each) Bit #1+, #2+ Bit holder One way bit holder Exclusive charger Result of calibration document Certification on calibration document / Traceability system figure Option Outside-dimension Charge about 3 hour /, continuation about 12-hour use After the neglect during 10 minutes HEX 6.35 HEX 6.35 Bit #1+, #2+ Bit holder One way bit holder Exclusive charger Result of calibration document Certification on calibration document / Traceability system figure When outputting data, the cable (USB miniB) is needed.	Power supply		Ni-MH chargeable battery 1.2V×4cells 800mAh
Auto-power-off Bit / Socket part HEX 6.35 Weight Accessories (one piece each) Bit #1+, #2+ Bit holder One way bit holder Exclusive charger Result of calibration document Certification on calibration document / Traceability system figure When outputting data, the cable(USB miniB) is needed.			
Weight Accessories (one piece each) Bit #1+, #2+ Bit holder One way bit holder Exclusive charger Result of calibration document / Traceability system figure Option Option Outside-dimension Weight 400g Bit #1+, #2+ Bit holder One way bit holder Exclusive charger Result of calibration document / Traceability system figure When outputting data, the cable(USB miniB) is needed.	Auto-power-off		After the neglect during 10 minutes
Accessories (one piece each) Bit #1+, #2+ Bit holder One way bit holder Exclusive charger Result of calibration document Certification on calibration document / Traceability system figure Option When outputting data, the cable(USB miniB) is needed.	Bit / Socket part		HEX 6.35
Accessories (one piece each) Bit #1+, #2+ Bit holder One way bit holder Exclusive charger Result of calibration document Certification on calibration document / Traceability system figure Option When outputting data, the cable(USB miniB) is needed.	Weight		400g
Accessories (one piece each) Bit holder One way bit holder Exclusive charger Result of calibration document Certification on calibration document / Traceability system figure When outputting data, the cable(USB miniB) is needed.	Accessories		
(one piece each) Exclusive charger Result of calibration document Certification on calibration document / Traceability system figure When outputting data, the cable (USB miniB) is needed.			Bit holder One way bit holder
Option Result of calibration document / Traceability system figure When outputting data, the cable(USB miniB) is needed. 237 Outside-dimension Outside-dimension			
Option When outputting data, the cable (USB miniB) is needed. 237 Outside-dimension 7 26 92			
Outside-dimension 237 T 26 92			
Outside-dimension 92 92 92	Option		When outputting data, the cable(USB miniB) is needed.
m/m	Outside-dimension		97 GEDAR Model DID-4 GEDAR MODE
			m/m

Please check the newest information and the details of each product in a homepage. **《URL http://www.cedar.co.jp》**



The contents of a catalog may change specification and a design without a preliminary announcement.